P.R.O.S. - Property Reports On Sight

San Antonio 210)615-PROS *210)615-7767



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Exterior of Property

EXTERIOR		Observed	Unobserved	See Additional Pictures/Needs Further Evaluation
1.	Roof/Trim	\square		
2.	Exterior Door	\square		
3.	Walls-All Around	\boxtimes		
4.	Front/Back/Side Door	\boxtimes		
5.	Porch/Patio/Deck	\square		
6.	Light Fixtures	\square		
7.	Mail Box		\boxtimes	
8.	Fences (Front & Rear)	\square		
9.	Driveway	\square		
10.	Lawn-Grass			
11.	Trees/Touching House	\boxtimes		
12.	Shrubs and Brushes	\boxtimes		
13.	Pool		\boxtimes	
14.	Other		\boxtimes	





Picture #3 Front View of House (Close Up)






Picture #7 Picture of AC Unit










Interior of Property:

Picture #10 Front Door including casing.



If no safety issues or deficiencies observed NO COMMENTS will be Made.

 ENTRY WAY 1. Visible Address 2. Walls/Paint 3. Floors 4. Front Door 5. Keyless Lock 6. Peephole 7. Light Fixtures 8. Other 	Observed	Unobserved	See Additional Pictu	res/Needs Further Evaluation	

Picture #11 Porch/Steps Picture #12 Entry/Foyer D-R-HOHETON -W If no safety issues or deficiencies observed NO COMMENTS will be Made. Living Room/Great Room Observed Unobserved See Additional Pictures/Needs Further Evaluation 9. Flooring \times 10. Walls/Paint $\overline{\times}$ 11. Light Fixture 12. Blinds/Drapes 13. Windows 14. Ceiling Fan X \boxtimes 15. Outlet/Switch Covers 16. Other **Picture #13 Living Room Picture #14 Living Room Floor**






Picture #15 Living Room Ceiling




Picture #16 Living Room Wall




Picture #17 Living Room Wall









Picture #27 Family Room Wall



Picture #28 Family Room Wall



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Kitchen	Observed	Unobserved See	Additional Pictures/Needs Further Evaluati	on
15. Flooring				
16. Walls/Paint	\boxtimes			
17. Ceiling	\boxtimes			
18. Light Fixtures				
19. Blinds/Drapes	\boxtimes			
20. Kitchen Counter/Back Sp	olash 🛛			
21. Sink/Faucet	\boxtimes			
22. Cabinet Under Sink				
23. Garbage Disposal	\boxtimes			
24. Refrigerator	\boxtimes			
25. Range/Oven				
26. Dishwasher				
27. Oven				

Picture #29 Kitchen




Picture # 30 Kitchen Floor



Picture #31 Sink/Faucet/Backsplash



Picture # 32 Inside Cabinet Under Sink



Picture # 34 Upper Cabinets



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Hallway/Stairway	Observed	Unobserved	See Additional Pictures/Needs Further Evaluation
28. Flooring			
29. Walls/Paint			
30. Light Fixture			
31. Outlet/Switch Covers			
32. Other		\square	

Picture #35 Floor/Stairs





If no safety issues or deficiencies observed NO COMMENTS will be Made. Master Bedroom Observed Unobserved See Additional Pictures/Needs Further Evaluation 33. Flooring \boxtimes 34. Walls/Paint \times 35. Light Fixture \langle 36. Blinds/Drapes 37. Windows 38. Ceiling Fan 39. Outlet/Switch Covers 40. Other Picture # 38 Ceiling (Fan/Smoke Detector?) **Picture #37 Master Bedroom Picture #39 Master Bedroom Floor** Picture # 40 Master Bedroom Wall






If no safety issues or deficiencies observed NO COMMENTS will be Made.







Picture #49 4th Bedroom Full Shoot



Picture # 50 Ceiling (Fan/Smoke Detector)



If no safety issues or deficiencies observed NO COMMENTS will be Made.

Not Applicable/Property does not have a 2nd Bathroom/This Section will go unused.

2 nd Bathroom	Observed	Unobserved S	See Additional Pictures	s/Needs Further Evaluation
78. Flooring				
79. Walls/Paint				
80. Ceiling/Exhaust				
81. Light Fixtures	\bowtie			
82. Blinds/Drapes	\square		/	
83. Window	\square			
84. Sink/Faucet	\square			
85. Cabinet Under Sink	\square			
86. Shower/Faucet	\square			\square
87. Tub/Faucet	\square			
88. Commode	\boxtimes			
89. Towel Racks	\boxtimes			
90. Other		\boxtimes		

Picture #51 2nd Bathroom Full Shoot



Picture # 52 Bathroom Floor





Picture #53 Sink and Faucets





Picture # 54 Inside Cabinet under Sink















Picture # 68 Drainage Issues



Interior Comments: AC filter present in grate at time of inspection, a ladder is required to reach filter; photo 64.

Additional Pictures



Comments: #69Separation in grout of rear left wall partition brickwork of Rear Patio framing, vertical gutter system adjacent.#71-72Separation in caulking along vertical edges of tile work to 2nd Bathroom shower/tub unit framing.